

CONSUMER  
PROTECTION



WISCONSIN  
DEPARTMENT OF  
AGRICULTURE,  
TRADE AND  
CONSUMER  
PROTECTION

**OFFICE LOCATION**

2811 Agriculture Drive  
Madison, WI 53708-8911

1-800-422-7128  
608-224-4960

# News

July 2014 Edition

## Dear Wisconsin Children's Safety Advocates:

In June 2014, the U.S. Consumer Product Safety Commission issued a total of **7 recalls relating to products affecting children**. Attached is a summary of the releases identifying the product, the problem, and what should be done with the recalled product.

We have found that not all of the recalls are picked up by the news media as they occur. This monthly summary will give you the opportunity to review all of the children's product safety recalls for the past month. If you are interested in a complete text of the recall, double click on the hyperlink at the end of the recall description. This will direct you to the recall notice located on the CPSC website.

- **phil&teds Recalls Infant Car Seat Adaptors for Strollers Due to Fall Hazard** ([14-198](#))
- **Lea Industries Recalls Bunk Beds with Bookcases Due to Risk of Entrapment** ([14-735](#))
- **SCOTT Recalls Speedster Bicycles Due to Fall Hazard** ([14-202](#))
- **Reebok-CCM Recalls Throat Collars Due to Laceration Hazard** ([14-211](#))
- **Stile Products Recalls Tern Folding Bicycles Due to Fall Hazard; Frames Can Crack** ([14-213](#))
- **Scott, Trek Recall Bicycles with SR Suntour Front Forks Due to Crash Hazard** ([14-215](#))
- **Roland Recalls Digital Pianos Due to Electrical Shock Hazard** ([14-738](#))

If you would like to sign up for the Keep Your Kids Safe newsletter, please subscribe at

[https://public.govdelivery.com/accounts/WIDATCP/subscriber/new?topic\\_id=WIDATCP\\_161](https://public.govdelivery.com/accounts/WIDATCP/subscriber/new?topic_id=WIDATCP_161) or contact Bobbi Erb at (608) 224-4955 or [bobbi.erb@wisconsin.gov](mailto:bobbi.erb@wisconsin.gov).

If you have any questions or want to file a complaint regarding an unsafe product, contact:

Wisconsin Department of Agriculture, Trade and Consumer Protection  
Bureau of Consumer Protection  
2811 Agriculture Drive  
Madison, WI 53708

## **KEEP YOUR KIDS SAFE**

**Release Number: (#14-198)** phil&teds, of Fort Collins, C.O., is announcing the voluntary recall of about 265 in the U.S. and 122 in Canada Travel System 26 (TS26) adaptors used to attach infant car seats to the following phil&teds stroller models, the Classic, Dot, Explorer, Hammerhead, Navigator, S3 and S4.

Compatible car seats include the Maxi Cosi Cabriofix, Maxi Cosi Mico, Maxi Cosi Pebble and Cybex Anton. The adaptors are two pieces of black plastic, one for the left side and one for the right side, that connect the stroller to the car seat. "TS26," "phil&teds," "L" for left, "R" for right and UPC "9 420015 7 4004" are printed on the adaptors.

**Problem:** The plastic adaptors used to connect an infant car seat to a stroller can crack, become unstable and break during use, posing a fall hazard to infants.

**What to do:** Consumers should immediately stop using the recalled adaptor and contact phil&teds for free replacement adaptors. You can contact phil&teds toll-free at (855) 652-9019 from 9 a.m. to 5 p.m. MT Monday through Friday or online at [www.phil&teds.com](http://www.phil&teds.com) and click on "Support," then "Upgrades and Recalls" for more information.



<http://www.cpsc.gov/en/Recalls/2014/phil&teds-s-Recalls-Infant-Car-Seat-Adaptors-for-Strollers/>

**Release Number: (#14-735)** Lea Industries, of High Point, N.C., has announced the voluntary recall of about 500 Lea Covington and Hannah Collections style bunk beds with bookcases. The beds were sold in twin over twin and full over full

sizes with accessories including a bookcase. The Covington Collection has a cherry finish and the Hannah Collection, a white finish. The Lea name and model information is printed on a label attached to the backside of the headboard on the bottom bunk and on the back of the bookcase.

**Problem:** The bunk bed can be assembled incorrectly, creating a space that exceeds the 1.88 inches allowed by the industry standard, posing an entrapment hazard to young.

**What to do:** Consumers should immediately check to see if they have the recalled bunk beds and then contact Lea Industries to determine if the bed is misassembled. A professional installer can be dispatched to raise the position of the bottom bunk bed and install new brackets on the bookcase. Lea Industries is contacting known customers directly. You can contact Lea Industries toll-free at (888) 770-7116 from 8 a.m. to 5 p.m. ET Monday through Friday or online at [www.leafurniture.com](http://www.leafurniture.com) and click on "Safety" for more information.



<http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/Lea-Industries-Recalls-Bunk-Beds-with-Bookcases/>

**Release Number: (#14-202)** Scott USA Inc. of Ketchum, I.D., announces the voluntary recalls about 2,000 model year 2014 SCOTT men's and women's road bicycles, models Speedster 30, Speedster 40, Contessa Speedster 25 and Contessa Speedster 35. The bikes have the brand name "SCOTT" and the model name "Speedster" on the frame. They were sold in

black and white with blue, green, purple or teal accents. The following serial number ranges are included in the recall: AS30500001–AS30504930, AS30700001–AS30704651, AS30900001–AS30903278, AS31100001–AS31103744 and AS40101604–AS40105463. The serial number is printed on a white sticker and embossed on the underside of the bicycle frame near the pedals.

**Problem:** The steerer tube in the front fork can break, posing a fall hazard.

**What to do:** Consumers should immediately stop riding the bicycle and take it to an authorized SCOTT dealer. Consumers with a recalled bicycle will receive a free replacement fork and have it installed at no cost.



<http://www.cpsc.gov/en/Recalls/2014/SCOTT-Recalls-Speedster-Bicycles/>

**Release Number: (#14-211)** Reebok-CCM of Montpelier, V.T., announces the voluntary recall of about 3,300 in the United States and 8,100 in Canada TCPRE Senior (SR) and Junior (JR) Goalie Throat Collars are black with white trim and the word “Reebok” is embroidered at the base of the collar. They have the BNQ certification mark screen printed and the words “Ballistic Nylon Ballistique”, “TCPRE SR or JR” and sizing information on the right side of the collar base. Affected products have the model number K101SR TCPRE or K101JR TCPRE located on the label sewn on the inside of each throat collar pad and on the outside of a polybag in which the product may have been sold at retail stores.

**Problem:** Throat collars have been decertified by BNQ in Canada due to the risk that a skate blade could penetrate the collar, posing a laceration hazard to the throat.

**What to do:** Consumers should immediately stop using the recalled throat collars and contact their local hockey dealer to return the product for a full refund or replacement, or contact Reebok-CCM for information on how to return the product directly to Reebok-CCM for a replacement or full refund. You can contact Reebok-CCM at (800) 451-4600 from 9 a.m. to 5 p.m. ET., Monday through Friday, or online at

[www.reebokccm.com](http://www.reebokccm.com) and click on Goalie Throat Collar Recall at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Reebok-CCM-Recalls-Throat-Collars/>

**Release Number: (#14-213)** Stile Products Inc., of Lakewood, C.A., is announcing the voluntary recall of about 650 in the U.S. and about 20 in Canada Link Uno, Link D7i, Link D8, Link P9, Link P7i, and Link P24h models of Tern brand adult folding bikes. These six models were sold in black/blue, black/green, black/grey, black/red dark grey/light grey, grey/orange and white/pink color combinations. “Tern” is printed on the front end of the top tube and on other portions of the frame. The model name is printed on the middle of the top tube. Recalled bicycles have a 10-character alphanumeric serial number that begin with either A11133 through A11137 or A11151 through A11213 stamped on the bottom bracket shell of the bike. An alphanumeric service tag number is located on the front of the seat tube and this number can be used to determine if the bicycle is affected by going to the firm’s website.

**Problem:** The bike’s frame can crack at the hinge on the top tube, posing a fall hazard.

**What to do:** Consumers should immediately stop using the bicycles and contact Stile Products or take the bike to an authorized dealer. Consumers will receive a free replacement frame and have it installed at no cost or they can upgrade their bike to one of three designated models at an additional cost.



<http://www.cpsc.gov/en/Recalls/2014/Stile-Products-Recalls-Tern-Folding-Bicycles/>

**Release Number: (#14-215)** Scott USA Inc. of Ketchum, I.D. and Trek Bicycle Corp., of Waterloo, W.I., is announcing the voluntary recall of about 5,200 forks on Scott bicycles and about 120,000 forks on Trek bicycles. SR Suntour front forks on 13 models of Scott and 11 models of Trek 2011, 2012 and 2013 bicycles. Recalled Scott bicycles have 700c wheels, disc brakes and one of the following Suntour front fork models: NEX or NCX. Bicycle model names and numbers are on the main frame of each bicycle in a location that varies by model. The model year can be identified by the color scheme of the bicycle frame.

**Problem:** The front fork can break, posing a crash hazard.

**What to do:** Consumers should immediately stop using the recalled bicycles. Consumers with recalled Scott bicycles should take them to an authorized Scott dealer for a free repair of the NEX model or a free replacement lower fork for the NCX model. Consumers with recalled Trek bicycles should take them to an authorized Trek dealer for a free repair of NEX, XCM and XCT models or a free replacement of the NRX model. You can contact Scott USA toll-free at (888) 607-8365, ext. 2012, from 8 a.m. to 6 p.m. CT Monday through Friday, or online at [www.scott-sports.com](http://www.scott-sports.com) and click on Safety and Recalls at the bottom of the page for more information. Trek at (800) 373-4594 from 8 a.m. to 6 p.m. CT Monday through Friday, or online at [www.trekbikes.com](http://www.trekbikes.com) and click on the Get Support button at the bottom of the page, then click on Safety & Recalls under Owner Resources for more information.



<http://www.cpsc.gov/en/Recalls/2014/Scott-Trek-Recall-Bicycles-with-SR-Suntour-Front-Forks/>

**Release Number: (#14-738)** Roland Corporation of Los Angeles, C.A., announces the voluntary recall of about 640 Roland model RD-800 Electronic Digital Pianos. The recalled product is an electronic piano keyboard that is 55 inches wide, 14.5 inches deep and 5.5 inches high. It is black and has 88 black and white keys. The front of the piano has a control panel with a color liquid crystal display (LCD) in the

center. **Problem:** The AC power cord can be connected to the XLR output jacks, posing an electrical shock hazard.

**What to do:** Consumers should immediately stop using the pianos, unplug the power cord from the wall outlet and the piano and contact Roland U.S. for a free repair kit or to locate an authorized dealer or service center to have the repair kit installed free of charge. You can contact Roland Corporation toll-free at (877) 339-5494 from 8:30 a.m. to 5 p.m. PT Monday through Friday or email [rd800update@rolandus.com](mailto:rd800update@rolandus.com), or online at [www.rolandus.com](http://www.rolandus.com) and click on "RD-800 Recall Notice" under Support at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/Roland-Recalls-Digital-Pianos/>